

III. MSC/PATRAN

III.1 OBJECTIVE

The objective of this manual is to introduce the users to the finite element modeling capability of MSC/PATRAN and to give hands on, end_to_end guided tour of the software. The manual shows users how to start MSC/PATRAN, create the geometry model, create the finite element mesh, define the element and material properties, create load case and the loads and boundary conditions, prepare data for the analysis, and finally postprocess the results. This manual does not replace the MSC/PATRAN User's manual (which can currently be browsed through in the online help menu), but provides sufficient information to start with.

III.2 INTRODUCTION

The finite element method is a proven technique for using computers to model a wide variety of engineering problems. Its application in the real world was hindered, however, by the amount of time spent both in producing the raw data to feed a Finite Element Analysis (FEA), and in interpreting the usually large volumes of results from the analysis. MSC/PATRAN is a software developed to provide a systematic approach towards making FEA modeling fast and accurate. It uses a simple step-by-step approach that helps to create, analyze and interpret a mathematically realistic model of the structure. This approach is built around geometric modeling, interactive computer graphics, and current finite element theory.

III.2.1 Engineering Functionality

The capabilities of MSC/PATRAN include:

- (i) A full set of tools for the creation of parameterized model geometry. In addition, MSC/PATRAN has Single Geometric Model (SGM) capability. SGM accesses geometry data, topology, and evaluators from the CAD (Computer Aided Design/Drafting) system without transformation and establishes and maintains associativity with the corresponding MSC/PATRAN finite element entities throughout the entire design and analysis process.
- (ii) Finite modeling tools for analysis model creation and verification, including mapped meshing, automatic surface meshing, and automatic tetrahedral solid modeling.
- (iii) A complete set of functional (loads, boundary conditions, and material/element properties) assignment capabilities, including the capability to assign these *directly* to the geometry or the finite element model. In application, this means that the finite element mesh can be deleted and the geometry remeshed without having to reapply the functional assignments. All functional assignments can be collected into load cases and named, modified or deleted at the user's discretion.
- (iv) PATRAN Command Language (PCL) for the customization of MSC/PATRAN, the performance of variance and design sensitivity studies, and automation of routine, repetitive tasks.

III.2.2 Graphical User Interface

The MSC/PATRAN user interface is form driven and truly intuitive, minimizing the time required to learn the system. At startup, after creating a new database or opening an existing one, the MSC/PATRAN user interface consists of a control panel, graphics window (view port), and a command/history window. The control panel controls the parameters for system tasks such as managing files, setting preferences, manipulating groups and graphics, as well as switching between interactive applications. The information displayed in the graphics window includes geometry, finite elements, applied loads, boundary conditions, analysis results and user defined annotation. The command/history window contains a record of all commands executed during a MSC/PATRAN session, as well as enabling commands to be entered from the keyboard.

III.2.3 Files

MSC/PATRAN modeling begins with opening a file (new or existing) using the FILE pick in the upper left corner of the main menu. File management options available under the FILE pick include: create a new database, open or close an existing database, access CAD geometry, import IGES models or PATRAN Neutral Files, record and playback session/journal files.

The MSC/PATRAN relational database defaults to a ".db" extension and contains a complete record of user created geometry, finite elements, load cases, load and boundary conditions, materials, element properties, preferences, and results. MSC/PATRAN database creation is memory expensive. Each database requires approximately 6MB of disk space. Therefore old database should be compressed using the Compact Database option under the FILE pull down menu.

The record of commands shown in the command/history window during a MSC/PATRAN modeling exercise are stored in editable files that can later be run through MSC/PATRAN to perform parametric or sensitivity analyses. Two files are created by MSC/PATRAN to store these commands:

- A session file (.ses extension) which contains the record of all PCL commands for each interactive session.
- A journal file (.jou extension) which contains a record of all PCL commands for a particular PATRAN database.

III.2.4 Analysis Preferences

MSC/PATRAN provides for the user unique analysis preferences i.e. a user can readily switch between commercial analysis solvers and proprietary in-house codes. Thus the user is not faced with having to learn the command and syntax of each particular analysis solver. Upon setting the new preference, MSC/PATRAN automatically updates common element properties, material properties, loads, boundary conditions, and analysis code forms to those of the newly selected solver. Note that in this manual, our analysis solver will be MSC/NASTRAN.

III.2.5 Results Visualization

MSC/PATRAN postprocessing is state-of-the-art in its ability to display, sort, combine, scale, and query in a general way a single results database. After execution, analysis results are loaded directly into the MSC/PATRAN relational database and can be sorted by time step, frequency, temperature or spatial location. MSC/PATRAN postprocessing enables the engineer to filter engineering results by material, element type and property, node and element IDs, thresholds of results, etc., *simultaneously*. Display types include but are not limited to: deformed, fringe, vector, tensor, and engineering X_Y plots. Shear and bending moment diagrams are available for beam results and a sophisticated text report writer is available to print out all results in a user defined sorting sequence and format. The insight application within MSC/PATRAN condenses mountains of raw numerical data into graphical tools and displays for complete, accurate interpretation of finite element analysis results.

III.2.6 On-Line Help/Documentation

The entire manual of MSC/PATRAN can be browsed through by clicking the left mouse button on the HELP button of the Top Menu Bar of the Control Panel. All interactive features, functions, and applications in MSC/PATRAN can be obtained from the completely topical and context sensitive help on-line. Hypertext links throughout the on-line system allow for instant retrieval of complex information. The MSC/PATRAN on-line help system eliminates the need for printed documentation, because the MSC/PATRAN printed documentation is *identical* to on-line help files.

III.3 LAB. SESSION 1

III.3.1 Things to know before you start

How to start MSC/PATRAN: After you are in the X-Window environment, just type '**cae-patran2005**' at the UNIX prompt.

Hardcopy Printout: You can get a black and white printout through the printer '**cae-yoda**'. The procedures for printing are shown in Section III.3.3. Generally the user prints into a postscript file. Then the file is sent to a printer of choice by using the '**lpr**' command, i.e.

lpr -Pcae-yoda filename

where '**printer**' is the name of the printer and '**filename**' is the postscript file generated.

How to quit MSC/PATRAN: To quit MSC/PATRAN, click the left mouse button on the '**File**' button of the control panel and select '**Quit**' from the pulled down menu. If you want to start work on another database without quitting P3/PATRAN, you can select '**Save**' instead of '**Quit**' to save the current database.


Next we will go through the following:

- The menu components of MSC/PATRAN.
- How to use the three-button mouse.
- A highlight of how to modify the view of a model.
- How to print the contents of a viewport.

III.3.2 Menu Components of MSC/PATRAN

MSC/PATRAN Control Panel

MSC/PATRAN's Control Panel appears at the top of the screen (example below). The selections on this panel are divided by a horizontal line. The selection above the line is MSC/PATRAN's Top Menu Bar, which includes MSC/PATRAN's heartbeat and the on-line help system. The items below the line are a group of radio buttons and a group of Control Panel icons.



The Menu Bar selections are pull-down menus which will be explained later in using the mouse (p.3.7)

Radio buttons are mutually exclusive choices in that only one radio button within a group can be pressed in at one time. They work like the radio buttons in your car. Only one button on your car radio can be pressed in at one time.

MSC/PATRAN's heart tells you if it is ready to execute an option or if it is busy executing.



Green means MSC/PATRAN is ready and waiting to execute a form.



Blue means it is busy, but it can be interrupted with the Hand icon.



Red means it is busy and it cannot be interrupted.

MSC/PATRAN's on-line help is an easy to use, hypertext-based documentation system. You can enter the on-line help either by pressing Help on the Menu Bar, or by placing the cursor anywhere on a MSC/PATRAN form and pressing the F1 key to get help on that particular form. If your cursor selects anything that is in magenta in the on-line help, MSC/PATRAN will quickly "jump" to another page in the on-line help that it is referencing.

The Control Panel icons are explained below:



Refresh Icon

Redisplays (refreshes) all of the graphics viewports



Display Cleanup Icon

Removes all fringe and marker plots, all automatic titles, highlighting and deformed shape plots. Repaints the viewport in wireframe mode



Interrupt Icon

Interrupts a command in progress. This is useful when you want to abort out of an executing MSC/PATRAN form




Undo Icon

Undoes the last executed action of a MSC/PATRAN form when an "Apply" was pressed

MSC/PATRAN Command Window

MSC/PATRAN also has a Command Window that appears at the bottom of the screen (see below). You *can* manually enter commands in this window, but mostly this window is used to view the commands MSC/PATRAN generates when a menu form is executed, and to view errors or information messages.



The command line. Commands
Can optionally be typed in here.

The history window. You can use the scroll
bars at the bottom and right sides to scroll back
or to scroll to the right.

MSC/PATRAN Application Form and Subordinate Form

The radio buttons on the Control Panel will bring up a vertical form on the right side of the screen. These forms are called the **Application forms**. There are also smaller forms that are sometimes displayed which are associated with the specific Application form, and they are called **Subordinate forms**.

III.3.3 Using the Mouse

MSC/PATRAN uses a three-button mouse. Depending on what you are doing, each of the three buttons will accomplish a specific task in MSC/PATRAN. The following is a summary of what you will need to know to complete the guided tour.

Using Pull-Down or Option Menus

To use a pull-down or option menu, with the left mouse button, click on menu item. While holding down the mouse button, drag the mouse to the appropriate selection and then, release the mouse button.

Selecting From a Listbox

A Listbox has a title at the top and a list of contents. To select an item, use the left mouse button and highlight the item. To deselect the item, use the left mouse button and highlight the item. To deselect the item, use the left mouse button and click on the highlighted item.

Overview of the Three Buttons

The left mouse button is used to select model entities. To select more than one entity, hold down the Shift key while selecting the entities with the left mouse button.

The right mouse button is used to deselect an entity that was selected in error. To deselect more than one entity, hold down the Shift key while selecting the entities with the right mouse button.

The center mouse button is used to change the view by rotating, translating, or zooming. Keep the button pressed down and drag the mouse to move the model.

Cursor Selecting Shortcuts

To cursor select model entities with a rectangular box, hold down the left mouse button at the upper left hand point and drag the cursor to the lower right hand point. Then, release the mouse button.

To cursor select entities with a polygon shape box, hold down the Control Key (Ctrl) and use the left mouse button and start picking at arbitrary points A, B, C, D, ... to define a closed polygon box.

III.3.4 Modifying the View

There are several ways to alter the view of your model, and below are some of the more common ways.

Using the Middle Mouse Button

As mentioned earlier, you can rotate, translate, or zoom in on your model by dragging the mouse, while holding down the middle mouse button. To switch the mouse function to rotate, translate, or zoom, enter **View/Mouse Settings...**

View/Select Corners...

You can zoom in on a particular part of your model, and at the same time, define a new viewing center by selecting from the Menu Bar:

MSC/PATRAN will turn the cursor into a cross-hatch. Define a new “viewport” by dragging the cursor diagonally and defining a rectangular box:

Drag the cursor along a diagonal direction to select a portion of the model you want to view up close.

Select **View/Fit View...** if you want to return the view back to the entire model.

View/Transformations...

You can rotate or translate the view incrementally by selection from the Menu Bar.

A subordinate *Transformations* form will appear with a matrix of buttons. By pressing any one of the buttons, you can translate, zoom, or rotate your model incrementally.

For example by pressing a button, MSC/PATRAN will rotate your model about the screen or model’s Y axis

To perform a “Fit View”, where MSC/PATRAN will resize the view of the model to fit within the viewport, you would simply press the assigned button.

More view/transformation buttons are shown on the next page.



Show the entire model with hidden lines



Show the entire model without hidden lines



Show the shaded solid view of the model



Show the end_view in the Y_X plane



Show the end_view in the Z_X plane



Show the end_view in the Z_Y plane



Show the isometric view




Show all the labels (set labels on)




Do not show all the labels (set labels off)

III.3.5 How to print the contents of the current viewport.

To print a hardcopy output of the contents of a viewport, the user should click the left mouse button on the '**File**' option of the top menu bar of the control panel and select '**Print**' in the pulled_down menu. The following application form is shown on the screen:



The user then selects "Postscript Default" under available printers and "Postscript" under Driver. The 'Page Setup...' option provides another form where the either landscape or portrait paper orientation can be selected. A third form is obtained by clicking on 'Options...' menu. This form, which is shown below, asks for the Format, Background, Lines & Text, etc. The form shown here has been completed for the generation of a postscript file named 'manual.ps' for black & white output.



To obtain a color postscript file, the 'Color' option is selected for 'Format', the 'White' option for 'Background' and the 'Actual' option for 'Lines and Text'.
To print the generated postscript file, simply type at the UNIX prompt:


lpr -Pprinter filename

where '**printer**' is the name of the printer and '**filename**' is the postscript file generated. Use '**cae-yoda**' for black and white printout.

III.3.6 Creating the Geometry


Each student should go through this section as part of Lab. Session 1. To enter MSC/PATRAN, just type "**cae-patran2005**" at the UNIX prompt. Wait until the system displays the control panel window and the command history window (see p. 4.4 & 4.5) for <SC/PATRAN.

The first step is to create a new database file. This is done by clicking the left mouse button on "FILE" in the top menu bar of the control panel. This will show a pull down menu from which "CREATE A NEW DATABASE" is selected. The result is the form shown below:



Note that one should click on "Modify Preference" to check whether MSC/NASTRAN is selected as the analysis before proceeding. In the form shown above, a new data base name

“manual” has been entered. The user can supply his/her own name. The OK button is selected With the left mouse to create a new database named “name.db” (in this example, manual.db). After the database has been created, the following form for model preferences is automatically displayed:



The image shows a 'New Model Preference' dialog box. It has a title bar with a blue background and a close button. The main area is light orange. It contains the following fields and options:

- Model Preference for:** cae_manual.db
- Tolerance:** A section with two radio buttons: 'Based on Model' (selected) and 'Default'.
- Approximate Maximum Model Dimension:** A text box containing the value '10.0'.
- Analysis Code:** A dropdown menu showing 'MSC.Nastran'.
- Analysis Type:** A dropdown menu showing 'Structural'.
- Buttons:** 'OK' and 'Reset' buttons at the bottom.

This form is completed for tolerance limit, approximate maximum dimension of the model to be created, analysis code of choice and analysis type. The form shown here has been completed for structural analysis with MSC/NASTRAN as the analysis code. As said earlier (see p.2), our analysis code will be MSC/NASTRAN. After the form is completed, "OK" button is selected.

The next step is to start the creation of a geometrical model. In this lab session, the reader is taken through creation of basic geometrical entities such as point, curve (1_D), surface (2_D), and solid (3_D).


The creation of all geometrical entities is initiated by clicking the left mouse button on the "GEOMETRY" radio button of the control panel (see p. 4.4). A typical form that needs to be completed is shown below (The left mouse button is used to move through the form). Note that in MSC/PATRAN, the input format of the coordinate of a point, (x, y, z) is given by [x, y, z], which is different from that of a vector given by < x, y, z >.

The screenshot shows a window titled "Geometry" with a standard Windows-style title bar (minimize, maximize, close buttons). The interface is divided into several sections:

- Action:** A dropdown menu set to "Create".
- Object:** A dropdown menu set to "Point".
- Method:** A dropdown menu set to "XYZ".
- Point ID List:** A text input field containing the number "1".
- Refer. Coordinate Frame:** A section containing a dropdown menu set to "Coord Q".
- Auto Execute:** A checkbox that is currently unchecked.
- Point Coordinates List:** A text input field containing the coordinates "[0 0 0]".
- Apply-:** A button at the bottom of the form.

The above form has been completed for the creation of a point at $(x,y,z) = [0,0,0]$. It should be mentioned here that there are several options under "Action", "Object", and "Method". The choice of combination of options for these three is based on the result desired. Further examples will be seen in the course of this manual. After a geometrical entity has been created, the figure shown below (Visible Entities) is seen at the bottom of the screen. This figure highlights geometrical entities that can be selected by clicking of the left mouse button on the desired entity. The second point is at $[5\ 0\ 0]$.

The figure below shows the view port after two points have been created.




The next stage is to create a curve. The form below has been completed for the creation of a 2_point curve using the two points created earlier:

A screenshot of the 'Geometry' dialog box. The 'Action' is set to 'Create', the 'Object' is 'Curve', and the 'Method' is 'Point'. The 'Curve ID List' contains the number '2'. The 'Option' is set to '2 Point'. There is a checkbox for 'Auto Execute' which is checked. The 'Starting Point List' contains 'Point 1' and the 'Ending Point List' contains 'Point 2'. At the bottom, there is an '-Apply-' button.

The result of applying the above form is shown below:


Next, we illustrate the creation of a 3_point arc. The third point is at [2.5, 2.5, 0]. For this purpose the completed form is shown below:



The screenshot shows a 'Geometry' dialog box with the following fields and options:

- Action:** Create
- Object:** Curve
- Method:** Arc3Point
- Curve ID List:** 3
- ☐ Create Center Point
- ☐ Auto Execute
- Starting Point List:** Point 1
- Middle Point List:** Point 3
- Ending Point List:** Point 2
- Apply-** button

Don't click on "Auto Execute." Instead, click on "Apply". It gives user a little room to correct typo errors. The result of applying the above form is the arc (curve 2) shown in the figure below:




The next stage is to create a surface. A surface can be created from 2, 3, 4, or N curves where N is a number to be supplied by the user. An example is given here of how the a surface can be created from two curves. First, the 3_point arc should be deleted by selecting "delete" under "action" and then clicking on the 3_point arc in the viewport. Next, the following form is completed for creating a second curve by translating the first 2_point curve:

The screenshot shows a 'Geometry' dialog box with the following fields and options:


- Action:** Transform
- Object:** Curve
- Method:** Translate
- Curve ID List:** 3
- Type of Transformation:**
 - ☒ Cartesian in Refer. CF
 - ☒ Curvilinear in Refer. CF
- Refer. Coordinate Frame:** Coord 0
- Translation Vector:** <0 5 0>
- Translation Parameters:**
 - Repeat Count:** 1
 - ☐ Delete Original Curves
 - ☐ Auto Execute
 - Curve List:** Curve 1
- Apply-** button at the bottom.

In the above form, "<0 5 0>" is entered for the "Translation Vector", and "Curve 1" is entered for the "Curve List". The result of applying this form is shown below:

Applying the above form, we have the result shown below:



The next stage is to create a solid. Again, there are several ways of creating a solid. In this example, we are using the 2_surface option. Hence we need to create another surface. This is done by translating the previous surface 5 units of distance in the z_direction (i.e. Translation Vector: $\langle 0 \ 0 \ 5 \rangle$). The form completed for surface translation is similar to that of curve translation with "Surface" as the "Object". After surface translation, we have the result below:



The rectangular solid is created by completing the form shown below:

Geometry

Action: Create

Object: Solid

Method: Surface

Solid ID List: 1

Option: 2 Surface

Parameterization Method

☒ Chord Length

☐ Uniform

☐ Auto Align Orientations


☐ Auto Execute

Starting Surface List: Surface 1

Ending Surface List: Surface 4


-Apply-

Applying the above form, we have the result shown below. To write a note or legend on the figure, click on “Display,” then “Title” and follow the instructions to fill out the proper information. Click on “Apply”. In the following picture, the title is given as Solid_Model.




III.4 LAB SESSION 2: Plate problem

In this lab session, try to create the plate shown below. The steps used in generating the plate are illustrated. You are not limited to using these steps. You can obtain the same results using any other combination of steps if you are confident of doing so.




Step 1: Enter MSC/PATRAN by typing '**cae-patran2005**' at the UNIX prompt.

Step 2: Create a new database named 'classwk1' (or any other name you prefer) by clicking on 'File/New Database' of the control panel. The following form is displayed. It is completed by supplying the new data base name.




Step 3: Set the model parameters by completing the model preferences form shown below. This form is automatically displayed after a new database has been created or an existing one opened.



The 'New Model Preference' dialog box is titled 'New Model Preference' with standard window controls. It contains the following fields and options:

- Model Preference for:** classwk1.db
- Tolerance:** A group box containing two radio buttons: 'Based on Model' (selected) and 'Default'.
- Approximate Maximum Model Dimension:** A text input field containing the value '15.0'.
- Analysis Code:** A dropdown menu showing 'MSC.Nastran'.
- Analysis Type:** A dropdown menu showing 'Structural'.
- Buttons:** 'OK' and 'Reset' buttons at the bottom.

Step 4: Start geometry creation by clicking on the 'Geometry' button of the radio panel. The following form is displayed. The form is completed for point 1 (at $[x \ y \ z] = [0 \ 0 \ 0]$) as shown.



The 'Geometry' dialog box is titled 'Geometry' with standard window controls. It contains the following fields and options:

- Action:** A dropdown menu showing 'Create'.
- Object:** A dropdown menu showing 'Point'.
- Method:** A dropdown menu showing 'XYZ'.
- Point ID List:** A text input field containing the value '1'.
- Refer. Coordinate Frame:** A dropdown menu showing 'Coord 0'.
- Auto Execute:** An unchecked checkbox.
- Point Coordinates List:** A text input field containing the value '[0 0 0]'.
- Buttons:** '-Apply-' button at the bottom.

Step 5: Similar to point 1, create points 2 and 3 at [x y z] of [5 0 0] and [0 3 0] respectively.

Step 6: Create point 4 by translation method. This is done by completing the form shown below. The form has been completed for creation of point 4 by translating point 3 through a vector of $\langle 5 \ 0 \ 0 \rangle$. The Point ID List is shown to be 5 because the 'Apply' button has been clicked on and point 4 has been created.

Geometry

Action: Transform

Object: Point

Method: Translate

Point ID List

5

Type of Transformation

☒ Cartesian in Refer. CF

☐ Curvilinear in Refer. CF

Refer. Coordinate Frame

Coord 0

Translation Vector

<5 0 0>

Translation Parameters

Repeat Count

1

☐ Delete Original Points

☐ Auto Execute

Point List

Point 3

-Apply-

Step 7: Similar to point 4, create point 5 by translating point 2 through $\langle 0 \ 1 \ 0 \rangle$.

Step 8: Similar to point 4, create point 6 by translating point 4 through $\langle 0.5 \ 0 \ 0 \rangle$.

Step 9: Similar to point 4, create point 7 by translating point 5 through $\langle 0.5 \ 0 \ 0 \rangle$.

Step 10: Similar to point 4, create point 8 by translating point 7 through $\langle 2 \ 0 \ 0 \rangle$.

Step 11: Similar to point 4, create point 9 by translating point 6 through $\langle 2 \ 0 \ 0 \rangle$.

Step 12: Similar to point 4, create point 10 by translating point 9 through $\langle 2.5 \ 0 \ 0 \rangle$.

Step 13: Similar to point 4, create point 11 by translating point 8 through $\langle 2.5 \ 0 \ 0 \rangle$.

Step 14: Similar to point 4, create point 12 by translating point 10 through $\langle 2.5 \ 0 \ 0 \rangle$.

Step 15: Similar to point 4, create point 13 by translating point 11 through $\langle 2.5 \ 0 \ 0 \rangle$.

Step 16: This step begins the creation of curves. Create a curve by selecting 'Curve' as 'Object' in the 'Geometry' form. The form is shown below completed and already applied (hence 2 is shown in the CURve ID List) to create curve 1. Curve 1 is created using the 2_point method and the points used are 1 and 2.

The screenshot shows the 'Geometry' dialog box with the following settings:

- Action:** Create
- Object:** Curve
- Method:** Point
- Curve ID List:** 2
- Option:** 2 Point
- ☒ **Auto Execute**
- Starting Point List:** Point 1
- Ending Point List:** Point 2
- Apply-** button at the bottom.

Step 17: Similar to curve 1, create curves 2 through 11 by using 'Starting Point List' 3, 4, 2, 5, 6, 7, 8, 8, 11, 13 and 'Ending Point List' 4, 6, 5, 7, 9, 8, 9, 11, 13, 12 respectively. In other words, curve 11, for example, is created by joining point 13 and point 12.

Step 18: Create curve 12 by using the '2D ArcAngles' option under 'Method'. A form to be completed for this is shown below. This form has been completed and applied for curve 12 (hence 13 is displayed in the 'Curve ID List'). For this curve, the following information was supplied: Radius (1.0), Start Angle (180), End Angle (225), Center Point List (Point 10).


The screenshot shows the 'Geometry' dialog box with the following settings:

- Action:** Create
- Object:** Curve
- Method:** 2D ArcAngles
- Curve ID List:** 13
- Arc Parameters:**
 - Radius:** 1.0
 - Start Angle:** 180.0
 - End Angle:** 225.0
- ☒ **Project to Plane**
- Construction Plane List:** Coord 0.3
- ☒ **Auto Execute**
- Center Point List:** point 10
- Apply-** button at the bottom.

Step 19: Similar to curve 12, create curves 13 through 15 using the same radius and center point list as curve 12 but with start angles 225, 270, 315 and end angles 270, 315, 360 degrees.

Step 20: Create curve 16 by using the 'Fillet' option under 'Method'. The region of fillet is shown in the plate figure. The form displayed to be completed is shown below. This form has been completed for the fillet curve. The following information was supplied: Fillet Radius (0.5), Curve/Point 1 List (click on curve 5, then point 5), Curve/Point 2 List (click on curve 4, then point 5). After the form is completed, P3 asks if the original curves should be trimmed. A window is displayed for this (see below). The option 'Yes' or "Yes For All" is selected.

A new point 19 and a new curve 16 are created. The result is shown below:



Step 21: Trim the curve between points 19 and 5 by using “Edit” under “Action”. Select “Trim” under “method” and “point” under “option.” Select “Trim” under “method” and “point” under “option”. Select point 19 and curve 4 for “Trim Point List” and “Curve/Point List”. Click on “Apply” after the form is completed.

The screenshot shows the 'Geometry' dialog box with the following settings:

- Action:** Edit
- Object:** Curve
- Method:** Trim
- Option:** Point
- ☐ Auto Execute
- Trim Point List:** Point 19
- Curve/Point List:** 9)(Evaluate Geometry(Curve 4))
- Apply-** button

This step involves merging of two curves 5 and 7. This is done by using the form below. The new curve formed from the merge is 17. The next two forms contain questions about the merging. The answer to the first question (Do you wish to create a duplicate curve?) is 'No'. The answer to the second question (Do you wish to delete the original curves?) is 'Yes'. Follow step 21 to trim the curve between points 5 and 7.

The screenshot shows the 'Geometry' dialog box with the following settings:

- Action:** Edit
- Object:** Curve
- Method:** Merge
- Curve ID List:** 17
- Merge Parameters:**
 - Number of Curves to Create:** 1
 - Merge Tolerance:** 0.007
 - ☐ Delete Original Curves
- Curve List:** Curve 5 7
- Apply-** button

The screenshot shows a 'Message' dialog box with the following content:

- Question from application SGM:** Do you wish to delete the original curves?
- Yes** button
- No** button

Step 22: Trim showed 10

Step 23: Create Surface 1 using the 2_curve option. This is done by completing the form shown below. The form has been completed and applied for surface 1 (hence it is ready for surface 2, i.e. Surface ID List = 2). The 'Starting Curve List' for surface 1 is 'Curve 16' and the 'Ending Curve List' is 'Curve 3'.

The screenshot shows a 'Geometry' dialog box with the following settings:

- Action:** Create
- Object:** Surface
- Method:** Curve
- Surface ID List:** 2
- Option:** 2 Curve
- Parameterization Method:** Chord length (selected), Uniform
- Manifold:** ☒ Manifold
- Manifold Surface:** 1
- Auto Execute:** ☒ Auto Execute
- Starting Curve List:** Curve 16
- Ending Curve List:** Curve 3
- Buttons:** -Apply-

Step 24: Similar to surface 1, create surfaces 2 through 7 with 'Starting Curve List' 2, 6, 12, 13, 14, 15 and 'Ending Curve List' 1, 17, 8, 9, 10, 11. For example, surface 3 is created from curves 6 and 17.

Step 25: Before we continue, we want to set the 'Display Property' such that only surface numbers will be displayed, the curve and point numbers will be hidden. This is done by clicking on the Display' button of the control panel followed by “Geometry” button. This option allows the surfaces to be displayed with the fewest number of parametric lines. Next, all label buttons in the 'Entity Types' section of the form are deactivated except the surface label button. The form is then applied.

Geometric Attributes

Number of Display Lines
0

Chordal Tolerance
0.001

0.00

Geometric Shrink
☐ Show Parametric Direction
☐ Show Free Faces

1

Point Size

Colors and Labels

Point:		<input type="checkbox"/> Label
Curve:		<input type="checkbox"/> Label
Surface:		<input checked="" type="checkbox"/> Label
TSurf:		<input type="checkbox"/> Label
Solid:		<input type="checkbox"/> Label

Show All Geometry Labels


Hide All Geometry Labels

Coordinate Frames...

Reset

Apply Cancel

Step 26: Finally to complete our plate geometry creation, we mirror the figure in the viewport which is half of our geometry. This done by completing the form below. The mirror plane normal is defined as $\{[0\ 3\ 0][0\ 0\ 0]\}$. The 'Surface List' is selected to include all existing surfaces (i.e surfaces 1 through 7).



The screenshot shows a 'Geometry' dialog box with the following fields and options:

- Action:** Transform
- Object:** Surface
- Method:** Mirror
- Surface ID List:** 15
- Define Mirror Plane Normal:** $\{[0\ 3\ 0][0\ 0\ 0]\}$
- Offset Parameters:**
 - Offset:** 0.0
 - ☒ Reverse Surface
 - ☐ Delete Original Surfaces
 - ☐ Auto Execute
- Surface List:** Surface 1:7
- Apply-** button

Step 27: The created geometry can then be printed by following the example shown on p. 4.11. The user is free to supply his/her own file name.

Homework: Lug Problem

Now as your homework, generate the geometry of the LUG shown below. It is not necessary for the patch numbers to match those given in the figure.


III.5 LAB SESSION 3: Analysis of the Plate problem

In this lab session, we will analyze the plate of lab session 2. In particular we will learn how to use the following radio buttons:

1. **Load/BCs:** To assign boundary conditions and loads
2. **Load Cases:** To create and load cases
3. **Finite Element:** To generate finite element mesh.
4. **Materials:** To assign material properties.
5. **Element Props:** To assign element properties.
6. **Analysis:** Interfaces with NASTRAN via PATNAS (PATran to NASTran) to generate bulk data file and submit the file to NASTRAN for analysis automatically; and via NASPAT (NASTran to PATran) to read in and translate the analysis (OUTPUT2 format) results.
7. **Results:** To graphically view analysis results.

To accomplish the above, we will follow the steps shown below.

Load the geometry of the plate generated in lab session 2. This is done by opening the MSC/PATRAN database saved in the lab session 2 by clicking on **File/Opening an existing database....** The form shown below is completed by supplying the 'Existing Database Name'; indicating the full path to the directory in which the database file is located. If P3 is entered from the directory that contains the existing database, this database is automatically displayed in 'Database List'. The database can then be selected by clicking on its name in the list.




III.5.1 Boundary Conditions

The next step is to assign boundary conditions. The desired boundary conditions is to fix the left edge of the plate, that is, to constrain all six degrees of freedom for the left edge. To achieve this, the '**Load/BCs**' radio button is clicked on. This will bring a display of the form shown below on the left. This form is completed as indicated. The 'New Set Name' for the boundary condition is 'fixed'. The new set name is just for the user to identify the data, it is not used in NASTRAN input file.


The image shows two side-by-side screenshots of software dialog boxes. The left dialog box is titled 'Load/Boundary Cond...' and contains the following fields and buttons: 'Action:' with a 'Create' button, 'Object:' with a 'Displacement' button, 'Type:' with a 'Nodal' button, 'Current Load Case:' with a 'Default...' button and 'Type:' set to 'Static', an 'Existing Sets' list box, 'New Set Name' with the text 'fixed', and buttons for 'Input Data...', 'Select Application Region...', and '-Apply-'. The right dialog box is titled 'Input Data' and contains: 'Load/BC Set Scale Factor' with the value '1.', 'Translations <T1 T2 T3>' with the value '<0,0,0>', 'Rotations <R1 R2 R3>' with the value '< 0,0,0>', 'Spatial Fields' with empty input fields, 'FEM Dependent Data...' button, 'Analysis Coordinate Frame' with the value 'Coord 0', and 'OK' and 'Reset' buttons.

To complete the boundary condition specification, we have to 'Input Data' and 'Select Application Region'. To input data, the 'Input Data...' button is clicked on and the form above on the right is displayed. This form is completed as indicated. The 'Translations' vector is $\langle T1 \ T2 \ T3 \rangle = \langle 0 \ 0 \ 0 \rangle$ and the 'Rotations' vector is $\langle R1 \ R2 \ R3 \rangle = \langle 0 \ 0 \ 0 \rangle$. This implies that the six degrees of freedom are constrained.

To select application region, the 'Select Application Region...' button is clicked on. This will bring a display of the form shown below. Since we are assigning the boundary conditions before the finite element mesh is generated, we select 'Geometry' under 'Geometry Filter'. Then the cursor is moved to 'Select Geometry Entities'. At this point, since we want to apply the boundary condition to the left edge of the plate, we first click on the edge icon in the 'Visible Entities' display (see page 4.14). The select menu will then state 'Select a Curve'. At this point, we cursor select the left edge of the plate by using a rectangular cursor selection. After this is done, 'Surface 2.1 9.4' (that is, edge 1 of surface 2 and edge 4 of surface 9) is shown in the 'Select Geometry Entities' window. We then click on 'Add' and 'Surface 2.1 9.4' is now shown in the 'Application Region' window. After this is completed, click on 'OK' to conclude this part.




Then press 'Apply' on the 'Load/BCs' Application Menu form to conclude the whole step. At this point, you should have the figure shown below. Notice the 'cones' at the left edge of the plate at the display lines' point location. These cones represent the three fixed translational and three fixed rotational boundary conditions. Notice that this boundary condition is applicable to any future finite element mesh generated for the plate, that is all finite element nodes on the left edge of the plate will have all six degrees of freedom constrained even though the nodes are yet to be created.



III.5.2 Applied Loads

The next step is to assign loads to the plate. In this example, we will have two point (nodal) loads, one in the negative Y_direction and the other in the positive X_direction, the lines of action of both forces passing through the center of the circular hole in the plate. To achieve this we complete the same set of forms as for the boundary conditions for each of the point loads, one after the other, but with the following modifications. The 'Object' is 'Force' rather than 'Displacement'. For the first point load, the 'New Set Name' of '1000_pound_down' can be used and for the second point load, '10000_pound_right' can be used. These names are just for the user's benefit, they are not used in NASTRAN's input file. In the 'Input Data...' form, the following force vectors are provided: $\langle F1 \ F2 \ F3 \rangle = \langle 0 \ -1000 \ 0 \rangle$ for the first point load and $\langle F1 \ F2 \ F3 \rangle = \langle 10000 \ 0 \ 0 \rangle$ for the second point load. For both loads, the moment vector is $\langle M1 \ M2 \ M3 \rangle = \langle 0 \ 0 \ 0 \rangle$ since no external moment is applied. In the 'Select Application Region...' form, when the cursor is in the 'Select Geometry Entities' window, the 'Point' icon is selected instead of the 'Curve' icon. For the first load, cursor select the point at the top of the line dividing surfaces 12 and 13. For the second load, cursor select the point at the middle of the right edge of the plate. After 'Apply' is pressed for each of the loads in the 'Application Menu' form, the figure below is the result. Notice the arrows drawn at the selected points signifying the 1000_pound force in the negative Y_direction and 10000_pound force in the positive X_direction. Each arrow is displayed as soon as the load corresponding to it is created.



Now a load case will be created that combines the two point loads and also the specified boundary conditions. This is done by clicking on the '**Load Cases**' button of the control panel. The following form is then displayed. Initially under 'Existing Load Cases', we have the 'Default' load case listed. This load case is always present in any analysis, irrespective of how many more load cases are created by the user. Then we specify the new 'Load Case Name' as 'lcase_1'. We make the new load case current. The user is free to give some description for the new load case under 'Description'. This is optional. The next step is to go to the list of 'Assigned Load/BCs Sets' and then select the combinations of loads and boundary conditions that will constitute the load case being created. For our example, we select all the loads and boundary conditions in this list to constitute our load case. This means that our load case is made up of 'Displ_fixed_bc', 'Force_10000_ibf' and 'Force_1000_ibf'. After the form is completed, we press on 'Apply' to conclude the creation of the load case. By now, we should see under 'Existing Load Cases' our newly created load case i.e. 'lcase_1'.

Load Cases

Action:

Existing Load Cases

Default
lcase_1

Filter

Load Case Name
lcase_1

☒ Make Current

Type:

Description

Assign/Prioritize Loads/BCs

Load Case Scale Factor
1.0

-Apply-

III.5.3 Mesh Generation

The next step is to create the finite element mesh for our plate. This step is divided into two, the first is to create mesh seeds for the curves bounding our geometry. Mesh seeds allow us to define exactly how many elements we want on a selected curve or edge of a surface or solid. The number of mesh seeds on a curve is equal to the number of elements on that curve. An example is given here of how to create 10 mesh seeds on curve 1 of our geometry. The radio button '**Elements**' is clicked on and the form below on the left is displayed. The form is completed as indicated. Mesh seeds are created for other curves one after the other such that surfaces 2 and 9 have 5x10 elements each, surfaces 1 and 8 have 3x4 elements each, surfaces 3 to 7 and 10 to 14 have 4x4 elements each.

After the mesh seeds have been created, the next thing is to create mesh for our geometry. This is achieved by selecting mesh as the 'object' in the form shown in the middle below. The 'type' of element is chosen as surface since we are dealing with a 2_D problem. The 'element topology' selected is 'Quad4', i.e., quadrilateral elements with four nodes. We select 'Isomesh' as our 'Mesher'. All these selections are then applied to all the surfaces 1 to 14 as indicated in the 'Surface List'. To select all surfaces, we can use the window cursor after we have clicked on 'Surface' icon in the 'Visible Entities' display. After the apply button is pressed, the entire geometry is subdivided into 'Quad4' elements.

Finite Elements


Action: Create

Object: Mesh Seed

Type: Uniform

Display Existing Seeds

Element Edge Length Data



Number of Elements

Element Length (L)

Number = 10

Auto Execute

Curve List

Curve 1

-Apply-

Finite Elements

Action: Create

Object: Mesh

Type: Surface

Output ID List

Node 423

Element 285

Elem Shape Quad

Mesher IsoMesh

Topology Quad4

IsoMesh Parameters...

Node Coordinate Frames...

Surface List

surface 1:14

Global Edge Length

Automatic Calculation

Value 0.1

Prop. Name: ... Name ...

Prop. Type: ... N/A ...

Select Existing Prop...

Create New Property...

-Apply-

Finite Elements

Action: Modify

Object: Node

Method Move

Auto Execute

Node List

Node 75


New Node Locations

Node 4

-Apply-

Before concluding the process of mesh generation, some modifications are made to the nodes at the interface of surfaces 8 and 9 and also the interface of surfaces 1 and 2. The modification involves making, at the interface, the nodes for surface 9 coincident with the corresponding nodes for surface 8 and the nodes for surface 2 coincident with the corresponding nodes for surface 1. This is achieved by moving the nodes to their new positions. An example is shown in the form above on the right where 'Node 75' is moved to coincide with 'Node 4'.

After all the modifications are completed, the plate with the generated element mesh looks as shown below. Note the skewness of the elements at the interfaces mentioned above in surfaces 2 and 9 where some nodes have been moved to coincide with the nodes in surfaces 1 and 8.




The process of mesh generation is completed by doing the 'Equivalencing' and 'Optimization'. Equivalencing forces nodes that are within some specified tolerance limit to coincide. The tolerance used here is 0.007. This means that any two or more nodes within 0.007 unit of distance from one another will be forced to coincide at the position of the node with the lowest node identification number within the group. Examples of nodes affected by "Equivalencing" are the nodes along the symmetry line and along lines common to adjacent surfaces. The form below is completed for 'Equivalence'.


Finite Elements	
Action:	Equivalence
Object:	All
Method:	Tolerance Cube
Option:	Retain lower node id
Nodes to be excluded	
<div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Equivalencing Tolerance	
0.007	
-Apply-	

Optimization is done to minimize the memory requirement of the global stiffness matrix by rearranging the elements of the matrix such that the storage bandwidth is reduced. The form below has been completed to 'Optimize'. The table below the form is a result of the optimization when the 'Apply' button is pressed. Notice the drastic reduction in the bandwidth after

optimization! Pressing 'OK' will make the table disappear.



The 'Finite Elements' dialog box has a title bar with a green 'X' icon and standard window controls. It contains three dropdown menus: 'Action' set to 'Optimize', 'Object' set to 'Nodes', and 'Method' set to 'Both'. Below these is a 'Minimization Criterion' section with four checked options: 'RMS Wavefront', 'Bandwidth', 'Profile', and 'Max Wavefront'. At the bottom, there is a 'Starting Node ID' text field containing the value '1' and an '-Apply-' button.




The 'Bandwidth Optimization Parameters (Node Quantity)' dialog box features a table with five columns: 'Sorted FEM', 'Bandwidth', 'Profile', 'Max Wavefront', 'Avg Wavefront', and 'RMS Wavefront'. The table contains three rows of data. Below the table is an 'OK' button.

	Bandwidth	Profile	Max Wavefront	Avg Wavefront	RMS Wavefront
Sorted FEM	232	8482	39	25,319403	27,041704
After C-M	25	4356	24	13,002985	13,427084
After G-P-S	24	4340	24	12,955224	13,363126

III.5.4 Material Selection

In this section, we will create the structural material that constitutes our elements. We start by clicking on the '**Materials**' button on the control panel. The form shown below on the left side is displayed. We complete the form as shown. Our material is isotropic and the properties will be input manually. We supply the material name under 'Material Name'. After this we click on the 'Input Properties' button and we have the form shown on the right side. In this second form, we select the constitutive model which in this case is 'Linear Elastic'. We also fill out the property sheet by supplying the shown values for 'Elastic Modulus', 'Poisson Ratio', and 'Density'. We then press 'Apply' to make the information active. We then press 'Cancel' to complete the process. We now see in the left side form under 'Existing Materials' the name 'Steel'.



Materials

Action: **Create**

Object: **Isotropic**

Method: **Manual Input**

Existing Materials

Filter

Material Name

steel


Description

Date: 14-Jan-06 Time: 09:46:38

Input Properties ...

Change Material Status ...

Apply



Input Options

Constitutive Model: **Linear Elastic**

Property Name	Value
Elastic Modulus =	1.8e8
Poisson Ratio =	0.3
Shear Modulus =	
Density =	0.0005
Thermal Expan. Coeff =	
Structural Damping Coeff =	
Reference Temperature =	

Temperature Dep/Model Variable Fields:

Current Constitutive Models:

OK Clear Cancel

III.5.5 Element Properties

This section deals with specification of properties of our elements. This is started by clicking on the '**Element Props**' button on the control panel. This gives a display of the form shown on the left below. This form is completed as indicated. The elements are 2_dimensional in geometry. Hence the element type chosen is 'shell'. The name 'plate_shell' is given to the property set being created. Under 'Option(s)' the material is chosen to be 'Homogeneous'.

The next step is to input the element properties. This is done by clicking the left mouse button on 'Input Properties...'. The form shown on the right below is then displayed. The form is completed as shown. The material name is 'steel' where steel is the material created in step 5. Notice that 'm:' precedes the material name. This indicates that the elements whose properties are being created are made of material 'steel'. The element thickness is specified to be '0.125'. For the problem we want to solve, the information supplied so far is sufficient. Thus the element properties creation is concluded by pressing 'OK' on this form and then 'Apply' in the left form.

“Select Members” box in “Application Region”. (Note that you can not type in the member numbers directly into “Application Region” box.) One can either type in the members selected (e.g. Node 1:10, Surface 1:14, ...etc.) or use the mouse to select the members by boxing out the members of concerns. Next, click on “Add” button. The ID numbers of the members selected will appear in the Application Region” box and then “Apply” in the left form.

The image shows two side-by-side screenshots of software dialog boxes. The left dialog is titled 'Element Properties' and the right is 'Input Properties'.

Element Properties Dialog:

- Action:** Create
- Object:** 2D
- Type:** Shell
- Prop. Sets By:** Name
- Filter:** [Empty]
- Property Set Name:** plate_shell
- Options:**
 - Homogeneous
 - Standard Formulation
- Input Properties ...** (button)
- Application Region:**
 - Select Members:** [Empty]
 - Add** (button)
 - Remove** (button)
 - Application Region:** [Empty]
- Apply** (button)

Input Properties Dialog:

Stan. Homogeneous Plate(CQUAD4)

Property Name	Value	Value Type
Material Name	mssteel	Mat Prop Name
[Material Orientation]		CID
Thickness	0.125	Real Scalar
[Nonstructural Mass]		Real Scalar
[Plate Offset]		Real Scalar
[Fiber Dist. 1]		Real Scalar
[Fiber Dist. 2]		Real Scalar

At the bottom of the 'Input Properties' dialog are buttons for **OK**, **Clear**, and **Cancel**.

III.5.6 NASTRAN Analysis

The next step is to submit our plate to NASTRAN for analysis. It should be mentioned here that MSC/PATRAN automatically generates the NASTRAN bulk data file (.bdf) and also submit the .bdf file to NASTRAN. The way we do this is shown here. The first thing is to click on the **Analysis** button of the control panel. We have the form shown on the left below. We want to analyze the 'Entire Model' in 'Full Run'. The 'Job Name' we supplied is 'classwk1'. The user is free to use any job name. Notice that the analysis code to be used is MSC/NASTRAN and the solution type is 'Structural'.

To select MSC/NASTRAN as the analysis code, go to **Preference** menu. Choose **analysis** option, then choose **MSC/NASTRAN** in the pop-up menu of **Analysis Code**.

The image shows two side-by-side screenshots of software dialog boxes.

The left dialog box is titled "Analysis". It has a blue title bar with standard window controls. The main area is divided into several sections:


- Action:** A dropdown menu set to "Analyze".
- Object:** A dropdown menu set to "Entire Model".
- Method:** A dropdown menu set to "Full Run".
- Code:** A text field containing "MSC.Nastran".
- Type:** A text field containing "Structural".
- Available Jobs:** A list box that is currently empty.
- Job Name:** A text field containing "classwk1".
- Job Description:** A text area containing "MSC.Nastran job created on 14-Jan-06 at 10:16:34".
- A section with five buttons: "Translation Parameters...", "Solution Type...", "Direct Text Input...", "Subcases...", and "Subcase Select...".
- An "Apply" button at the bottom.

The right dialog box is titled "Translation Parameters". It also has a blue title bar with standard window controls. The main area is divided into several sections:



- Data Output:** A section with checkboxes for "OP2", "XDB", "Print", and "Punch". Below these are "OUTPUT2 Requests:" with a dropdown set to "P3 Built In", and "OUTPUT2 Format:" with a dropdown set to "Binary".
- Tolerances:** A section with three text fields: "Division:" set to "1.0e-08", "Numerical:" set to "1.0e-04", and "Writing:" set to "1.0e-21".
- Bulk Data Format:** A section with "Sorted Bulk Data:" set to "No", "Card Format:" set to "either", and "Grid Precision Digits:" set to "1".
- Node Coordinates:** A dropdown menu set to "reference frame".
- MSC.Nastran Version:** A text field containing "2004".
- Number of Tasks:** A text field containing "1".
- A group of checkboxes: "Write Properties on Element Entries", "Write Continuation Markers", "Convert CBARS to CBEAMS", and "Use Iterative Solver".
- External SuperElement Meth:** A dropdown menu set to "None".
- Buttons for "Numbering Options..." and "Bulk Data Include File...".
- At the bottom, "OK", "Defaults", and "Cancel" buttons.

When the 'Translation Parameters...' button is clicked on, we have the form displayed on the right above. All default values in this form are accepted. Notice that we have 'OP2 and Print' under 'Data Output' This ensures that results will be printed both in the NASTRAN OUTPUT2 format and the .f06 ascii format. Furthermore, the OUTPUT2 request is going to be done via the P3 built_in automatically.


Clicking on the 'Solution Type...' button will give the form shown below. The form is accepted as defaulted by pressing "OK".



The next step is to create subcases for the analysis. This is done by clicking on 'Subcase Create...' which then displays the form on the left below. To make lcase_1 (i.e. the load case created earlier) a possible subcase, we click on lcase_1 under 'Available Load Cases' and then press apply. This will place lcase_1 under 'Available Subcases'. To make requests for the variables we want in our output for this subcase, we click on 'Output Requests...' and we have the form on the right below. In this form, we click on 'Displacements', 'Element Stresses' and 'Constraint Forces' one after the other under 'Select Result Type'. Pressing 'OK' will place these three output requests under 'Output Requests' as indicated. The indicated output requests will be printed both in the .f06 and .op2 files. We then press 'Cancel' to conclude this selection. We then press 'Apply' in the form on the left to conclude 'Output Requests' and 'Cancel' to conclude 'Subcase Create'.




The last step is to select the subcases (out of the subcases created above) that will be used for analysis. This is done by clicking on 'Subcase Select...'. This will display the form shown below. We click on lcase_1 under 'Subcases For Solution Sequence: 101' and then press 'OK'. This will place lcase_1 under 'Subcases Selected'. Thus lcase_1 has been selected for analysis. We then press 'Cancel' to conclude this step.



After all these have been concluded, we press 'Apply' on the main application menu form and MSC/PATRAN starts the creation of classwk1.bdf (the bulk data file for the job 'classwk1'). At this point, the user waits until this process is completed. After the creation of classwk1.bdf, MSC/PATRAN automatically submits the file for analysis to NASTRAN without the user intervention. At the conclusion of NASTRAN analysis, we will now have in the current directory, among the files generated by NASTRAN, classwk1.op2 (the binary OUTPUT2 format result file) and also classwk1.f06 (an ascii result file). At this point we are set for post processing to see graphically our results.

III.5.7 Post Processing

The post processing procedure begins by translating the binary NASTRAN output2 (.op2) file using 'MSC/PATRAN'. This is done by clicking on the 'Analysis' radio button. When the required form is displayed (shown below), the option 'Read Output2' is chosen under 'Action', 'Both' is chosen as 'Object' and 'Translate' is chosen as 'Method'.



Analysis

Action:

Object:

Method:

Code:

Type:


Available Jobs

Job Name

Job Description

MSC.Nastran job created on 14-Jan-06 at 10:16:34

Clicking on '**Translation Parameters...**' will bring the form shown on the left below. All settings in this form are accepted as default. Clicking on '**Select Results Files**' will bring the form shown on the right below. The user then supplies the .op2 file in '**Selected Results File**'. This can be done by clicking on the required .op2 file under '**Available Files**'. In this example, we have '**classwk1.op2**' under '**Available Files**'. We then press 'OK' to accept our selection and 'Cancel' to conclude this step.



Translation Parameters

MSC.Nastran
Both
Translation Parameters

Tolerances

Division:

Numerical:

MSC.Nastran Version:

Additional Results to be Imported


☐ Rotational Nodal Results

☐ Stress/Strain Invariants

☐ Principal Directions

☐ P-element P-order Field

Element Results Positions:



Select File

Filter:

Directories



..
./desktop-vortex
./desktophost
./dt
./emacs.d
./fmU20kjp.b1bC

Files

baseframe_stiffener_062005.op2
baseframe_stiffeners.op2
bridge_061505.op2
classwk1.op2
connector.op2
for_csa_rajesh_free_maglev.op2
free_vehicle_rajesh_forcsa.op2


Selected Results File

When the translation process is completed, we are ready to view our results. This is achieved by clicking on the '**Results**' radio button on the control panel. We then have the form shown below on the left in which we have chosen '**Basic**' as the '**Form Type**'. The result for our load case, i.e., load_case_1, is automatically placed under '**Select Result Cases**'. We then click on our load case name as shown on the right below and the results that can be displayed by fringe plotting are indicated under '**Select Fringe Result**' while those that can be displayed line plotting are indicated under '**Select Deformation Result**'.




Clicking on '**2.1 _ Displacements, Translational**' under '**Select Deformation Result**' will lead to the display of the deformed shape shown below.

Clicking on '**3.1 _ Stress Tensor**' under '**Select Fringe Result**' will lead to a display of the fringe plot of the stress tensor superimposed on the deformed shape as shown below.




III.5.8 Homework

For the lug shown on page 4.29 (whose geometry you have generated), specify the loads and boundary conditions indicated in the figure. Also generate a suitable finite element mesh and perform NASTRAN analysis. Submit a print out of the deformed shape and the fringe plot of the Von Misses Stresses.



III.6 LAB SESSION 4: 1D Beam Problem using Bar Elements

The objective of this lab session is to demonstrate the use of the '**Element Props**' radio button for problems involving one dimensional bar or beam elements. The example problem is the frame shown below which is made up of 1D straight curves. Geometry creation, boundary conditions and loads assignment, load case creation, finite element mesh generation, material properties assignment, submission of job to NASTRAN for analysis and post processing can be handled in a manner similar to the last example. Hence, enough information will only be provided to guide us through the example. Necessary detailed explanations will be given under '**Element Props**'



III.6.1 Geometry

Points 1 to 8 in the above figure are at (x y z) of [0 1 0], [1 1 0], [1 1 1], [0 1 1], [0 0 0], [1 0 0], [1 0 1], [0 0 1] respectively. 2-Point straight curves are generated as shown by connecting points 1 and 2, 2 and 3, 3 and 4, 1 and 5, 2 and 6, 3 and 7, 1 and 4, and finally, 4 and 8.

III.6.2 Load/BCs

All six degrees of freedom are constrained for points 5 through 8, that is '**Translations**' and '**Rotations**' vectors are both equal to <0 0 0>. Force vectors of <0 -120 50> and <30 40 0> act at points 1 and 3 respectively. For both points, the moment vector is <0 0 0>. A load case with any name the user wants is created from the specified boundary conditions and the imposed point forces.

III.6.3 Mesh Generation

First mesh seeds are created, one mesh seed per curve. Thus each curve is represented by one element. After this, a mesh is created to connect the nodes created by the mesh seed operation. During mesh creation, in the '**Application Menu**' form, '**Curve**' is chosen under '**Type**' and '**Bar2**' is chosen under '**Element Topology**'. Under '**Curve List**', the entire geometry is chosen, i.e. Curves 1 through 8. '**Equivalencing**' and '**Optimization**' steps are carried out as usual.

III.6.4 Material Selection

An isotropic material with '**Elastic Modulus**' of 3.E7 and a '**Poisson Ratio**' of .33 is specified in the '**Input Properties...**' form. You can specify any name for the material under '**Material Name**'.

III.6.5 Element Properties

Proceed with element properties' specification as in the previous example. However in the '**Element Props Application Menu**' form, '**Object**' should be '**1D**' and '**Type**' should be '**Beam**'. Under '**Options**' select '**General Section**'. In this example, even though the section properties of the bar elements are the same, the elements belong to three different groups, each group having its own orientation vector. Therefore, three property sets will be assigned, each set for each orientation vector. The first orientation vector is for the elements in the two curves parallel to the x_axis, the second is for the elements in the two curves parallel to the z_axis, and the third is for the elements in the four curves parallel to the y_axis. The user is free to supply '**Property Set Name**' of choice for each of these sets. For the first property set, '**Input Properties...**' is clicked on and the appropriate form is displayed. A portion of this form is shown below.

Property Name	Value	Value Type
[Section Name]	[na:]	Properties
Material Name		Mat Prop Name
Bar Orientation		Vector
[Offset @ Node 1]		Vector
[Offset @ Node 2]		Vector
[Pinned DOFs @ Node 1]		String
[Pinned DOFs @ Node 2]		String

Create Sections
I C L ...
Beam Library
Assoc. Beam Section

OK Clear Cancel

The information required to be supplied in the above form are listed below. Where a particular information is applicable to our example, the required value (real scalar or vector) is given in front of the information. The values given are for the first property set, i.e. for curves parallel to the x-axis.

Material Name: m:steel (Note: Material name 'steel' is used for illustrative purpose)

Bar Orientation: [1 1 0] (Note: This is the orientation vector, V . See p. 2.25 of the manual).

[Offset @ Node 1]: Not applicable, skip.

[Offset @ Node 2]: Not applicable, skip

[Pinned DOFs @ Node 1]: Not applicable, skip.

[Pinned DOFs @ Node 2]:

Area: 8.0 (Note: This is a real scalar)

[Inertia 1, 1]: 10.667 (Note: See p. 2.16 of the manual).

[Inertia 2, 2]: 2.667

[Inertia 2, 1]: Not applicable, skip.

Torsional Constant: 13.334 (Note: This is ' J '. See p. 2.17 of the manual)

[Shear Stiff, Y]: 0.8333 (Note: See p. 2.17 of the manual).

[Shear Stiff, Z]: 0.8333

[Nonstructural Mass]: Not applicable, skip.

[Y of Point C]: 2. (Note: See p. 2.17 of the manual).

[Z of Point C]: 1.

[Y of Point D]: 2.

[Z of Point D]: _1.

[Y of Point E]: _2.

[Z of Point E]: _1.

[Y of Point F]: _2.

[Z of Point F]: 1.

Station Distances: Not applicable, skip.

For the curves parallel to the y-axis, the vector of 'Bar Orientation' is [1 1 0] while for the curves parallel to the z-axis, the vector is [0 1 1]. Every other information is the same as for the curves parallel to the x-axis.

III.6.6 NASTRAN Analysis

Submit your job for NASTRAN analysis following the steps in III.5.6 of the plate problem. Be sure to confirm the load cases and boundary conditions before submitting job for analysis.


III.6.7 Post Processing

Perform the post processing of your NASTRAN .op2 result following the steps in Section III.5.7 of the plate problem. In the '**Result Menu Form**' shown below, select '**Von Mises**' (stress quantity to be reported) as the option under '**Result Quantity**' and select '**6_At Center**' (the position where stress quantity will be reported) under '**Position**' at point C which implies that the stress at Point C defined in Section 6.5 will be reported.

The image shows a 'Results' dialog box with the following components:

- Action:** Create
- Object:** Quick Plot
- Four icons: a document with a cursor, a grid, a plot, and a 3D model.
- Select Result Cases:** A list box containing 'Default, Static Subcase'.
- Select Fringe Result:** A list box containing 'Bar Stresses, Axial', 'Bar Stresses, Bending', 'Bar Stresses, Maximum Combined', 'Bar Stresses, Minimum Combined', and 'Constraint Forces, Translational'.
- Position...(At Point C):** A button.
- Quantity:** A dropdown menu set to 'von Mises'.
- Select Deformation Result:** A list box containing 'Constraint Forces, Translational' and 'Displacements, Translational'.
- Animate:** A checkbox.
- Apply:** A button at the bottom.

The fringe plot of the Von Mises stresses is superimposed on the plot of the deformed shape as shown below.



III.6.8 Homework

Construct the model baja frame given below using MSC/PATRAN. The coordinates of the points are given. Connect these points with bar elements. The frame is subjected to the following forces: 100 lbf in the negative z-direction at point 8, 50 lbf in the positive x-direction at point 17, 120 lbf in the negative z-direction at point 17, 130 in the negative z-direction at each of points 1 and 2, and 150 lbf in the negative z-direction at each of points 24 and 26. Points 7, 10, 23 and 25 are the points of connection for the wheels. Constrain these points in the x, y, z, directions. The direction is left free because of the wheels. Use aluminum for the frame. Perform NASTRAN analysis to compute the deformation and the Von Mises stresses in the frame.